evolar

HEAT PUMP COVER
INSTALLATION INSTRUCTIONS

SILENTBOX DELTA S PLUS



Evolar
Mercuriusstraat 5
6541 BM Nijmegen
The Netherlands

T +31 (0)24 2120369
www.evolarshop.com

EN

v.2023 /
06

TOOLS REQUIRED FOR ASSEMBLY (NOT INCLUDED)

HAMMER	TAPE MEASURE	DRILL	BORER pr.8x60	IMBUS 4
HEADER 8mm	KNIFE			

PACKAGE CONTENTS

142x SCREW M6x16 DIN 7380	20x SCREW M6x60 DIN 7380	142x WASHER 6 DIN 125A	20x WASHER 8 PLAST	10x TEX 4,8x16
13x MNA-Z 8x50	5m DOUBLE-SIDE TAPE	18m EPDM SEAL	2x DELTA S PLUS 1	2x DELTA S 2
2x DELTA S PLUS 6	2x DELTA S 8	2x DELTA S 9	1x DELTA S PLUS 67	2x DELTA S 13
1x DELTA S 14	2x DELTA S 24	2x DELTA S 17	2x DELTA S 18	1x DELTA S 19
 1x DELTA S 23	1x DELTA S 60	1x DELTA S 61	2x DELTA S PLUS 8	1x DELTA S PLUS 66
2x DELTA S PLUS 65	2x DELTA S PLUS 6	2x DELTA S PLUS 1	 1x DELTA S 21	1x DELTA S 22
DELTA S 63	DELTA S 64	DELTA S PLUS 65		



X1 (mm):	X2 (mm):
2900	1900

SILENTBOX ACOUSTIC COVER COMBINATION AND DISCHARGE



ACOUSTIC COVER DISCHARGE DIRECTION

ASSEMBLY POINT NO.: 3.1.; 3.2.; 3.3.

ACOUSTIC COVER DISCHARGE DIRECTION

ASSEMBLY POINT NO.: 4.1.; 4.2.; 4.3.

ACOUSTIC COVER SUCTION DIRECTION

ASSEMBLY POINT NO.: 6.1.; 6.2.; 6.3.; 6.4.

ACOUSTIC COVER SUCTION DIRECTION

ASSEMBLY POINT NO.: 7.1.; 7.2.; 7.3.; 7.4.

1.



2.

2x	2x			
DELTA S PLUS 1	DELTA S 2	TAPE MEASURE	HAMMER	
			13x	12x
BORER pr.8x60	DRILL	IMBUS 4	MNA-Z 8x50	SCREW M6x16 DIN 7380
2x	12x			
GAMA S PLUS 6	WASHER 6 DIN 125A			





2.1.


DELTA S 2
DELTA S PLUS 6
DELTA S PLUS 6
DELTA S PLUS 1
DELTA S PLUS 1
DELTA S 2
12x SCREWM6x16 DIN
7380 WASHER M6 DIN
125A

2.2.


Ø8 (12x)
BORER pr. 8mm x
60mm (12x)
50

2.3.


12x MNA-Z 8x50
ADHESIVE EPDM GASKET AFTER CIRCUMFERENCE

3.1.

	2x	1x	1x
DIRECTION OUTLET	DELTA S 9	DELTA S 24	DELTA S 17

1x	 1x	11x	11x	
GAMA S 21	GAMA S 22	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4

10x	10x	
SCREW M6x60 DIN 7380	WASHER 8 PLAST	NŮŽ













3.2.

1x	10x	10x	
DELTA S 60 / 61	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



3.3.

2x
DELTA S 8



4.1.

	2x	1x	1x
DIRECTION OUTLET	DELTA S 9	DELTA S 24	DELTA S 17

1x	1x	11x	11x	
DELTA S 21	DELTA S 22	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4

10x	10x	
SCREW M6x60 DIN 7380	WASHER 8 PLAST	KNIFE



4.1.



4.2.

1x	10x	10x	
DELTA S PLUS 66 / 67	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



4.3.

2x

DELTA S 8



5.1.

2x	4x	4x	
DELTA S PLUS 65	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



5.2.

1x	7x	7x	
DELTA PLUS 66 / 67	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



5.3.

2x	6x	6x	
DELTA S PLUS 8	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



6.1.

	1x	1x	
DIRECTION INLET	DELTA S 24	DELTA S 18	IMBUS 4

7x	7x
SCREW M6x16 DIN 7380	WASHER 6 DIN 125A



6.2.

1x	13x	13x	
DELTA S PLUS 63 / 64	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



6.3.

1x	12x	12x	
DELTA S 18	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4

1x
DELTA S T7



6.4.



7.1.

DIRECTION INLET

1x DELTA S 17

1x DELTA S 24

IMBUS 4

10x SCREW M6x16 DIN 7380

10x WASHER 6 DIN 125A



7.2.

1x DELTA S PLUS 63 / 64

13x SCREW M6x16 DIN 7380

13x WASHER 6 DIN 125A

IMBUS 4



7.3.

2x	12x	12x	
DELTA S 18	SCREW M6x16 DIN 7380	WASHER 6 DIN 125A	IMBUS 4



7.4.



8.1.

2x	8x	
DELTA S 13	TEX 4,8x16	HEADER 8mm



8.2.



1x

DELTA S 12





SHORT THE PART AS NEEDED





8.3.

1x

DELTA S 14

10x

SCREW M6x16 DIN 7380

10x

WASHER 6 DIN 125A

IMBUS 4

KNIFE

10x SCREW M6x16 DIN 7380 WASHER 6 DIN 125A





DELTA S 14



REMOVE PART DELTA S 14 AND FAN ENCLOSURE WITH DOUBLE-SIDED ADHESIVE TAPE

TO DELTA PART S 14 CUT FACE SHAPE ON HEAT PUMP





8.4.	1x	10x	10x	
	DELTA S 19	SCREW M6x60 DIN 7380	WASHER 8 PLAST	IMBUS 4

1x

DELTA S 23



TIGHTEN CAREFULLY







evolar